Inspection Report

Name of Work: Improvements to 1st Main road at Munikondappa Layout in Ward No 14

B.R.No: 897/31.01.2015

Estimate Cost: 6.00 Lakhs

Bill Amount: 599046.00

Date of Inspection 19-03-2016.

Observation and Conclusion:

The above said work was shown to one by the Concerned Ward Engineer

The above said work is inspected by one along with the Concerned Ward Engineer.

The work done is satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಬಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073

Name of Work: Improvements to 1st Main road at Munikondappa Layout in Ward No 14

BR No. 897/14-15, Date.31.01.2015

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಮಾಗಡಿ ರಸ್ತೆ, ಬೆಂಗಳೂರು - 560 073

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to 1st Main road at Munikondappa Layout in Ward No 14

BR No. 897/14-15, Date.31.01.2015

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಶಾಗಲಗುಂಟೆ, ಬೆಂಗಳೂರು - 560 073.

MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements to 1st Main road at Munikondappa Layout in Ward No 14

BR No. 897/14-15, Date.31.01.2015



ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಜ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಸಾಗಲಗುಂಟೆ. ಬೆಂಗಳೂರು - 560 073

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT